



December 11, 1989

Mr. Dave Darby
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

RE: In Mine Monitor Station

MW-3

Dear Mr. Darby:

This is pursuant to our previous conversation pertaining to the status of the Genwal Coal Company in-mine monitor well MW-3. Due to the location of MW-3 (a pillar section), it is our concern that the location will be lost either to pillaring, caving or the area will be sealed off. I would request a meeting with you to discuss our options to mitigate this situation.

Should you have any questions or need additional information, please feel free to contact me at 687-9813.

Sincerely,

GENWAL COAL COMPANY

Allen P. Childs Mine Manager

tr